ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	1	Kempegowda Ward
Street ID	**Street Name**	**Significant Landmark**
I0359	NA	BB road Yelahanka
Segment No.	**Total Length (m)**	
1/S-I0359/S112733	1162.26	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	1,162.26	77.600382	13.103724	77.594336	13.095106	W0256	M0009

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Providing Kerb painting work and laying missing covering slabs and kerb stones at BB road Yelahanka in ward no 01 Yelahanka Sub-Division Yelahanka zon	1200000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Others	painting work and laying missing covering slabs an
Tender	**Work Details**	**Job No. / Work Code**
Tender	Providing Kerb painting work and laying missing covering slabs and kerb stones at BB road Yelahanka in ward no 01 Yelahanka Sub-Division Yelahanka zone	001-16-000015
Work Order No.	**Work Order Date**	**Period of Extention**
EE (YNK.D)/E-PMT-1/WO/29/2015-16	24/02/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/08/2016	29/08/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
R SATHEESH		0.00
Phone No.	**E-Mail ID**	
9164370941		

Field Inspection Details

Number of Trees	Any Other Information	Name
1		CHANDRASHEKAR
Date of Inspection	**Remarks**	
08/03/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA Ward No: 1 Ward Name: Kempegowda Ward Street ID: I0359

Date: 08/03/2017 Time: 00:41:39 RH20170308004139

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	08/03/2017	06/04/2017	COMPLETED
SE	VASU K M	08/03/2017	06/04/2017	COMPLETED
EE	VASU K M	08/03/2017	06/04/2017	COMPLETED
AEE	DEVARAJ	08/03/2017	06/04/2017	COMPLETED
AE	CHANDRASHEKAR	08/03/2017	06/04/2017	COMPLETED
AE	CHANDRASHEKAR	07/03/2017	06/04/2017	COMPLETED